



Visual DMIS Inspection Report

Part ID	A150001	Operator	Song
Part SN	1#	Phone	
Time	19:51:02 2024/12/27	Remark	

1 MM/ISO 1101



	NOM	ACT	DEV	-TOL	+TOL	OUTTOL
Profs	0.0000	0.0904	0.0904		0.1000	OK

